FORM HMC 1109

#### .Approved For Release 2001/03/04 : CIA-RDP81B00879R000500120042-2-COPY / OF 4

#### HYCON MFG. COMPANY

SYCAMORE 5-4241 TELEPHONES 707 SO. RAYMOND AVENUE PASADENA, CALIFORNIA

sold to Gentlemen

INVOICE

PE 15217

DATE

11-8-57

YOUR ORDER No.

BC-200

TERMS:

Net 30 days

JOB ADDRESS

JOB No.

Lot II, Schedule III


Contract Item No.			Rec. Insp. Report	Unit Price	Total Price
2	Spares Per Ex	khibit "E"			
	Line Item	No. of Units			
	24 30	1 ~ 1 ~	13081 13104	1,675.00 650.00	1,675.00
5	1 Production U	Jnit	13172	850.00	850.00
7	l'Production (	Jnit	12937 V	135.00	135.00
8	I Production U	Jnit	12970 😭	275.00	275.00
10	l'Production U	Jnit	12971	75.00	75.00
15	2 Production t	Jnits	13192	168.00	336.00
	Amount Due				\$3,996.00

I certify that the above bill is correct and just and that payment therefore has not been received.

HYCON MFG. COMPANY

FOIAb3a





Approved For Release 2001/03/04 : CIA-RDESSI

RECEIVING INSPECTION REPORT

Approved For Release 2007/03/1945. CAMPDIP81B00879R000500 20142120 4

RECEIVED FROM DATE REC'D. 26 30, tember 1957 FLANT # P.O. NO.\_ VENDOR PACKING SLIP NO. CONTRACT DRAWING NUMBER DWG. DASH OR STANDARD PART NO. DWG. REV. LOT NO. CLASS NUMBER OPER. BUY OUT NUMBER 0 ACCT, OR W.O. NO.\_ CHARGE TO 735540 R B 91 QUANTITY RECEIVED DRAWING NO. AND DESCRIPTION QUANTITY REMARKS ACCEPTED REJECTED Schedule III Contract Item 2 Line Item 30 1 Box, Electrical Test Model 73-C IP9 #3063 FOIAb3a FOIAb3a CLA-RDP81B00879R000500120042-2

RECEIVING INSPECTION REPORT

## \* Approved For Release 2009/03/04%. CDA4RDP81B00879R000500120042129 2

RECEIVED FROM DATE REC'D. 4 Jetober 1947 PLANT A P.O. NO .-CONTRACT CODE NO. VENDOR PACKING SLIP NO. DRAWING NUMBER DWG. DASH OR STANDARD PART NO. DWG. LOT NO. CLASS NUMBER OPER. NUMBER BUY OUT REV. 0 ACCT. OR W.O. NO. 441 735370 CHARGE TO 51 O R QUANTITY RECEIVED DRAWING NO. AND DESCRIPTION QUANTITY REMARKS ACCEPTED REJECTED Schedule III Contract Item 15 2 735370 Cart Assembly, Film Loading Block 73-B Serial #'s 7 & 8 IF 3077 FOIAb3a FOIAb3a IA-RDP81B008<u>79</u>R00<u>05001</u>2004

RECEIVING INSPECTION REPORT

### \*Approved For Release 200408/049: CDA/PADP81B00879R000500120042127 2

RECEIVED FROM DATE REC'D. 2 (000) 1937 PLAST M P.O. NO. CONTRACT CODE NO. VENDOR PACKING SLIP NO. DRAWING NUMBER DWG. DASH OR STANDARD PART NO. BUY OUT CODE NO. CLASS NUMBER OPER. NUMBER REV. 0 ACCT, OR W.O. NO. 440 73526C G 51 R QUANTITY RECEIVED DRAWING NO. AND DESCRIPTION QUANTITY REMARKS ACCEPTED REJECTED 1 735260 Test Set, Oyro Eleck And Vibra-Lion Detector Ser. 1 Schedule III Contract Item 1/6 /301 FOIAb3a FOIAb3a RECEIV BY RDP81B90879R900500120042-2

RECEIVING	INSPECTION	DEDODT
VECELATIAN	INSPECTION	KFP()KI

# RECEIVING INSPECTION REPORT roved For Release 200908/09: CPARDP81B00879R0005001001420281

•	, 5							DATE F		C'D. 9-57
1000		PLANT.								
HARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBE	BUY OUT	OR	ACCT, OR W.O. NO.
DUANTITY		DRAWING NO	AND DECE	<u> </u>	!	1	OLLAN	TITY	<u> </u>	s.o. No
RECEIVED		DIAWING NO.	AND DESCRIPTION	N		ACCE	QUAN	REJECTED	$\exists$	REMARKS
1	Schedu. 735320	le III Contrac Mature-Opti	t Ites 2 Mne enl Pixture M				,			
		17% /305	7				3B)			
5										FOIAb3a
FOIAb3a	a		,							alnala
EI				C	IA-F	RDB81	B008	R79R001	0.5 EM	7/ <i>7 // /</i> 600120042-2 JO NO.

RECEIVING	INSPECTION	REPORT

RECEIVING INSPECTION REPORT
Approved For Release 200403/049. CPAMRIDIP81B00879R0005001200429271

RECEIVED FF	ROM		2781 E. COLORAD	O ST., PA	ASADENA	, CALIF.			
		Plent						DATE R	EC'D. 8-32-57
الروسية فأس	CONTRACT	DRAWING						VENDOR PA	ACKING SLIP NO.
()	CODE NO.	NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBE	BUY OUT	O ACCT. OR
CHARGE TO QUANTITY	44	735626	16	C	56	2		1 1	R W.O. NO
RECEIVED	1	DRAWING NO. A	AND DESCRIPTIO	N -			QUAN	TITY	
,						ACCE	PTED	REJECTED	REMARKS
1	735626-1	le III Contro lé Dolly, Le 24" Ser.	W Bed Transac	ort la	i y				Shop
O		IF8 #303	7				-		FOIAb3a
FO	lAb3a								
		,				1	1		7 06/0

RECEIVING INSPECTION REPORT

• 200408/046. CLAARDP81B00879R0005001201429270

		ved i di ivele	2961 E. COLORAD	O ST PA	SADENA	CALLE			ON INCOMPENDED	
RECEIVED FF	ROM	<b>N</b>	"		SADEITA	, OALIF.		ATE RE	C'D.	***
		Plant,	79					P.O. NO		
	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER NUMBER	BUY OUT	KING SLIP NO.	<del>.</del>
CHARGE TO	44	735616		A	55			R	M/O NO	
QUANTITY RECEIVED		DRAWING NO. A	AND DESCRIPTIO	N		ACCE	QUAN		REMARKS	
1	73%18		t Item 8 d Stand Assy		/	ACCE	/	REJECTED	Mustoco.	
						1			proportion.	
ř.		123	#3039			38	3	ř.	·	
									FOIAb3a	
F	DIAb3a	,								
RECEIVED					17-	 	Sand-	700005	9/1V/6	$ \leftarrow $
(ECEIVEI)					81 KB7 LJ			,,,,,,,,,,,,,,		

CEIVED FR	ОМ	PLAN	2961 E. SOLORAD		10/10/11/1			DATE REC	C'D	
	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG.	LOT NO.	CLASS NUMBER	OPER.	BUY OUT	KING SLIP NO.	
RGE TO	44	735605		C	55			R	ACCT, OR W.O. NO	
ANTITY		<del></del>	D. AND DESCRIPTIC	)N	197	ACCE	QUAN	TITY REJECTED	REMARKS	
1	735605		hedule III T	Hen	- 1		/-		nu Stort	
		Sen	sitemeter				/_		nu Stort	
1		Sen				,	/_		nu Stort	FO
		Sen	sitemeter	, i Ch			/_		mu Stort	FŒ
<b>3</b>		Sen	sitemeter	, Cn			/_		nu Stort	F